


www.howardkeys.com

Howard Keys® "The KEY People"

8:00 AM - 6:00 PM Mon-Fri EST
Charlotte, NC • Fernley, NV
Mississauga, ONT, CAN


SAME DAY SHIPPING **1-800-524-9199**

NO MINIMUM ORDERS HANDLING CHARGES



BHD106-PT5
\$7.95 ea.

↕ CLONING TOOL
REQUIRED ↕




BHD106-PT
\$7.95 ea.

↕ SPECIAL EQUIPMENT
REQUIRED ↕




HD106-PT5-HK
\$6.95 ea.

↕ CLONING TOOL
REQUIRED ↕



BHO01T5
\$10.50 ea.

↕ CLONING TOOL
REQUIRED ↕



BHO01-PT
\$13.95 ea.

↕ SPECIAL EQUIPMENT
REQUIRED ↕

Warehouse Locations



**2007 Application
Listings Enclosed**

Att: Parts Manager
**ACURA
HONDA**

VOL 13


ACURA			Code Series	ALL METAL		PLASTIC HEAD	
				Full Box 50 Per Box	Open Quantity 10 Per Bag	Full Box 25 Per Box	Open Quantity 5 Per Bag
TL, TSX	2004-07	All	5001-8442	→ TRANSPONDER N/A ←			
TL & CL	99-2003	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
NSX	97-2004	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
RL	97-2006	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
MDX, RDX(07)	2001-07	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
RSX	2002-06	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
INTEGRA	2000-01	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
VIGOR	2002-04	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			

*Cloning Tool Required Prices subject to change. Terms of Sale: Net F.O.B. Warehouse


HONDA			Code Series	ALL METAL		PLASTIC HEAD	
				Full Box 50 Per Box	Open Quantity 10 Per Bag	Full Box 25 Per Box	Open Quantity 5 Per Bag
ACCORD Sedan, Coupe	2003-07	All	High Security	→ TRANSPONDER N/A ←			
	97-2002	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
CR-V	2006-07	All	5001-8442	→ TRANSPONDER N/A ←			
	2002-05	All	High Security	→ TRANSPONDER BHO01T5* \$ 10.50 ea. ←			
CIVIC	2006-07	All	High Security	→ TRANSPONDER N/A ←			
	2003-05	All	High Security	→ TRANSPONDER BHO01T5* \$ 10.50 ea. ←			
	2001-02	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
INSIGHT	2000-06	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
ODYSSEY, FIT (07)	2005-07	All	High Security	→ TRANSPONDER N/A ←			
	2003-04	All	High Security	→ TRANSPONDER BHO01T5* \$ 10.50 ea. ←			
	98-2002	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
ELEMENT, PILOT	2006-07	All	High Security	→ TRANSPONDER N/A ←			
	2003-05	All	High Security	→ TRANSPONDER BHO01T5* \$ 10.50 ea. ←			
PASSPORT	98-2002	All	5001-8442	HD103 .40 ea.	.50 ea.	HD103-P .75 ea.	.90 ea.
PRELUDE	97-2002	All	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
S2000	2006-07	All	High Security	→ TRANSPONDER N/A ←			
	2004-05	All	High Security	→ TRANSPONDER BHO01T5* \$ 10.50 ea. ←			
	2000-03	Master	5001-8442	→ TRANSPONDER HD106-PT5-HK* \$ 6.95 ea. ←			
RIDGELINE	2005-07	All	5001-8442	→ TRANSPONDER N/A ←			

We believe the above applications are accurate; however, due to possible production changes we cannot guarantee them.


*Cloning Tool Required Prices subject to change. Terms of Sale: Net F.O.B. Warehouse




B65
Box/50 .50 ea.
Bag/10 .60 ea.




B65-P
Box/25 .85 ea.
Bag/5 1.00 ea.



B74
Box/50 .50 ea.
Bag/10 .60 ea.




B74-P
Box/25 .80 ea.
Bag/5 .95 ea.




HD90
Box/50 .40 ea.
Bag/10 .50 ea.




HD90-P
Box/25 .75 ea.
Bag/5 .90 ea.




HD92
Box/50 .40 ea.
Bag/10 .50 ea.




HD92-P
Box/25 .60 ea.
Bag/5 .75 ea.




HD93
Box/50 .75 ea.
Bag/10 .85 ea.




HD94
Box/50 .75 ea.
Bag/10 .85 ea.




HD95
Box/50 .75 ea.
Bag/10 .85 ea.




HD96
Box/50 .40 ea.
Bag/10 .50 ea.




HD96-P
Box/25 .80 ea.
Bag/5 .95 ea.




HD97
Box/50 .75 ea.
Bag/10 .85 ea.




HD98
Box/50 .40 ea.
Bag/10 .50 ea.




HD98-P
Box/25 .75 ea.
Bag/5 .90 ea.




HD99
Box/50 .80 ea.
Bag/10 .90 ea.




HD99-P
Box/25 .80 ea.
Bag/5 .95 ea.




HD100
Box/50 .65 ea.
Bag/10 .75 ea.




HD100-P
Box/25 .75 ea.
Bag/5 .90 ea.




HD101
Box/50 .55 ea.
Bag/10 .65 ea.




HD101-P
Box/25 .70 ea.
Bag/5 .85 ea.




HD102
Box/50 .55 ea.
Bag/10 .65 ea.




HD102-P
Box/25 .75 ea.
Bag/5 .90 ea.



HD103
Box/50 .40 ea.
Bag/10 .50 ea.



HD103-P
Box/25 .75 ea.
Bag/5 .90 ea.



HD104
Box/50 .55 ea.
Bag/10 .65 ea.




BHD106-PT5
\$7.95 ea.

CLONING TOOL
REQUIRED



BHD106-PT
\$7.95 ea.


SPECIAL EQUIPMENT
REQUIRED



HD106-PT5-HK
\$6.95 ea.




CLONING TOOL
REQUIRED




BHO01T5
\$10.50 ea.

CLONING TOOL
REQUIRED



BHO01-PT
\$13.95 ea.

SPECIAL EQUIPMENT
REQUIRED



HO01-SVC
Box/50 .70 ea.
Bag/10 .80 ea.